

Replacement Manual

FOR Minolta bizhub C200/203/253/353/8650 chip, Develop +200/203/253/353 chip

And Olivetti MF 201/201+/250+/350+ chip.



(1) Open the door.



(2) And then pull out the Imaging unit.



(3) Use a screw driver to release screws and take out the OEM chip.



(3) Install compatible new chip.

For more information, contact us as below:

E-mail: info@tonerchips.com